

Client: North Smithfield School Dept.  
Address: 450 Greenville Road  
North Smithfield, 02896

Warwick, RI Phone# (401) 461-3993  
ASBESTOS INSPECTION FORM

Project Inspector: Kenneth Beliveau

Contact: Halliwell Bldg #9 (was #10)

Date: 12/30/05

Type of Inspection: 6 month surveillance

| Location            | Suspect Material     | Approx. Amount | Friable | ACBM?   | No Damage | Phys. Damage |      | Accessible | Phys. Damage | Water Damage | Potential |          | Response Action | 6 month Surveillance |
|---------------------|----------------------|----------------|---------|---------|-----------|--------------|------|------------|--------------|--------------|-----------|----------|-----------------|----------------------|
|                     |                      |                |         |         |           | <10%         | >10% |            |              |              | Damage    | Sig. Dam |                 |                      |
| Front Entrance Area | 1x1 CT large dot     |                |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                     | ceramic floor        | 66 sf          | no      | assumed | x         |              |      | x          |              |              |           |          | M8              | N                    |
|                     | window glazing       | 8 sf           | no      | yes     | x         |              |      | x          |              |              |           |          | M8              | N                    |
|                     | doors                | 2              | no      | assumed | x         |              |      | x          |              |              | x         |          | M7              | N                    |
|                     |                      |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
| Left Classroom      | 9x9 FT/A             | 825 sf         | no      | yes     | x         |              |      | x          |              |              | x         |          | M7              | N                    |
|                     | 2x4 CT fiss/pinhole  |                |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                     | 1x1 CT large dot     |                |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                     | counter top material | 50 sf          | no      | yes     | x         |              |      | x          |              |              | x         |          | M7              | N                    |
|                     | window glazing       | 8 sf           | no      | yes     | x         |              |      | x          |              |              |           |          | M8              | N                    |
|                     | chalk board          |                | no      | assumed | x         |              |      | x          |              |              |           |          | M8              | N                    |
|                     | caulk board          |                |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                     | doors                | 3              | no      | assumed | x         |              |      | x          |              |              | x         |          | M7              | N                    |
|                     |                      |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                     |                      |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                     |                      |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                     |                      |                |         |         |           |              |      |            |              |              |           |          |                 |                      |

T=Thermal, S=Surfacing, M=Miscellaneous  
REM=Removed

6 Month Inspection; N=No Change, R=Repaired, D=Damaged,

Client: North Smithfield School Department  
Address: 450 Greenville Road  
North Smithfield, 02896

Warwick, RI Phone# (401) 461-3993  
ASBESTOS INSPECTION FORM

Project Inspector: Kenneth Beliveau

Contact:   
Project Location: Halliwell Bldg #9 (was #10)

Date: 12/30/05  
Type of Inspection: 6 month surveillance

| Location        | Suspect Material     | Approx. Amount | Friable | ACBM?   | No Damage | Phys. Damage |      | Accessible | Phys. Damage | Water Damage | Potential |         | Response Action | 6 month Surveillance |
|-----------------|----------------------|----------------|---------|---------|-----------|--------------|------|------------|--------------|--------------|-----------|---------|-----------------|----------------------|
|                 |                      |                |         |         |           | <10%         | >10% |            |              |              | Damage    | Sig Dam |                 |                      |
| Right Classroom | 9x9 FT/A             | 825 sf         | no      | yes     | x         |              |      | x          |              |              | x         |         | M7              | N                    |
|                 | 2x4 CT fiss/pinhole  |                |         | no      |           |              |      |            |              |              |           |         |                 |                      |
|                 | 1x1 CT large dot     |                |         | no      |           |              |      |            |              |              |           |         |                 |                      |
|                 | counter top material | 50 sf          | no      | yes     | x         |              |      | x          |              |              | x         |         | M7              | N                    |
|                 | window glazing       | 8 sf           | no      | yes     | x         |              |      | x          |              |              |           |         | M8              | N                    |
|                 | chalk board          |                | no      | assumed | x         |              |      | x          |              |              |           |         | M8              | N                    |
|                 | caulk board          |                |         | no      |           |              |      |            |              |              |           |         |                 |                      |
|                 | doors                | 3              | no      | assumed | x         |              |      | x          |              |              | x         |         | M7              | N                    |
|                 |                      |                |         |         |           |              |      |            |              |              |           |         |                 |                      |
| Bathroom Area   | ceramic floor        | 148 sf         | no      | assumed | x         |              |      | x          |              |              |           |         | M8              | N                    |
|                 | 1x1 CT large dot     |                |         | no      |           |              |      |            |              |              |           |         |                 |                      |
|                 | window glazing       | 4sf            | no      | yes     | x         |              |      | x          |              |              |           |         | M8              | N                    |
|                 | ceramic wall         |                | no      | assumed | x         |              |      | x          |              |              |           |         | M8              | N                    |
|                 | doors                | 6              | no      | assumed | x         |              |      | x          |              |              | x         |         | M7              | N                    |
|                 |                      |                |         |         |           |              |      |            |              |              |           |         |                 |                      |
|                 |                      |                |         |         |           |              |      |            |              |              |           |         |                 |                      |
|                 |                      |                |         |         |           |              |      |            |              |              |           |         |                 |                      |

T=Thermal, S=Surfacing, M=Miscellaneous  
REM=Removed  
6 Month Inspection; N=No Change, R=Repaired, D=Damaged,

Client: North Smithfield School Dept.  
Address: 450 Greenville Road  
North Smithfield, 02896

Client: \_\_\_\_\_

Project Location: **Haliwell Bldg #9 (was #10)**

Warwick, RI Phone# (401) 461-3993  
**ASBESTOS INSPECTION FORM**

Project Inspector: Kenneth Beliveau  
\_\_\_\_\_

Date: 12/30/05  
Type of Inspection: 6 month surveillance

| Location                  | Suspect Material       | Approx. Amount | Friable | ACBM?   | No Damage | Phys. Damage |      | Accessible | Phys. Damage | Water Damage | Potential |          | Response Action | 6 month Surveillance |
|---------------------------|------------------------|----------------|---------|---------|-----------|--------------|------|------------|--------------|--------------|-----------|----------|-----------------|----------------------|
|                           |                        |                |         |         |           | <10%         | >10% |            |              |              | Damage    | Sig. Dam |                 |                      |
| Boiler Room               | plaster walls/ceilings | 120 sf         |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                           | flex duct              | 4 sf           |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                           | doors                  | 1              | no      | assumed | x         |              |      | x          |              | x            |           |          | M7              | N                    |
| Exterior                  | Transite ceiling       | 1,285 sf       | no      | yes     | x         |              |      | x          |              | x            |           |          | M7              | N                    |
| Basement interior as well | Transite siding        | 180 sf         | no      | yes     | x         |              |      | x          |              |              |           | x        | M4              | N                    |
|                           | roof shingles          | 2,482 sf       | no      | assumed | x         |              |      |            |              |              |           |          | M8              | N                    |
|                           | roof mastic            | 10 sf          | no      | assumed | x         |              |      |            |              |              |           |          | M8              | N                    |
|                           | chimney sleeve         | 4 lf           | no      | assumed | x         |              |      |            |              |              |           |          | M8              | N                    |
| Above Ceilings            | duct insulation        | 100 sf (est.)  | yes     | assumed | probable  |              |      |            | x            |              |           | x        | T5              | N                    |
|                           |                        |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                           |                        |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                           |                        |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                           |                        |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                           |                        |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                           |                        |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                           |                        |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                           |                        |                |         |         |           |              |      |            |              |              |           |          |                 |                      |

T=Thermal, S=Surfacing, M=Miscellaneous  
REM=Removed

6 Month Inspection; N=No Change, R=Repaired, D=Damaged,

Client: North Smithfield School Dept.  
Address: 450 Greenville Road  
North Smithfield, 02896

Warwick, RI Phone# (401) 461-3993  
ASBESTOS INSPECTION FORM

Project Inspector:

Kenneth Beliveau

Contact:

Project Location: Halliwell Bldg #1 (was #1)

Date: 12/30/05

Type of Inspection: 6 month surveillance

| Location            | Suspect Material     | Approx. Amount | Friable | ACBM?   | No Damage | Phys. Damage |      | Accessible | Phys. Damage | Water Damage | Potential |          | Response Action | 6 month Surveillance |
|---------------------|----------------------|----------------|---------|---------|-----------|--------------|------|------------|--------------|--------------|-----------|----------|-----------------|----------------------|
|                     |                      |                |         |         |           | <10%         | >10% |            |              |              | Damage    | Sig. Dam |                 |                      |
| Front Entrance Area | 1x1 CT large dot     |                |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                     | ceramic floor        | 66 sf          | no      | assumed | x         |              |      | x          |              |              |           |          | M 8             | N                    |
|                     | window glazing       | 8 sf           | no      | yes     | x         |              |      | x          |              |              |           |          | M 8             | N                    |
|                     | doors                | 1              | no      | assumed | x         |              |      | x          |              | x            |           |          | M 7             | N                    |
|                     |                      |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
| Left Classroom      | 9x9 FT/A             | 825 sf         | no      | yes     |           | 16 sf        |      | x          |              |              |           | x        | M 3             | N                    |
|                     | 2x4 CT fiss/pinhole  |                |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                     | 1x1 CT large dot     |                |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                     | counter top material | 50 sf          | no      | yes     | x         |              |      | x          |              | x            |           |          | M 7             | N                    |
|                     | window glazing       | 8 sf           | no      | yes     | x         |              |      | x          |              |              |           |          | M 8             | N                    |
|                     | chalk board          |                | no      | assumed | x         |              |      | x          |              |              |           |          | M 8             | N                    |
|                     | caulk board          |                |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                     | doors                | 3              | no      | assumed | x         |              |      | x          |              |              | x         |          | M 7             | N                    |
|                     |                      |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                     |                      |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                     |                      |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                     |                      |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                     |                      |                |         |         |           |              |      |            |              |              |           |          |                 |                      |

T=Thermal, S=Surfacing, M=Miscellaneous  
REM=Removed

6 Month Inspection; N=No Change, R=Repaired, D=Damaged,



Kenneth Beliveau

Date: 12/30/05

Type of Inspection: 6 month surveillance

REM=Removed

Client: North Smithfield School Dept.  
Location: 450 Greenville Road  
Address: North Smithfield, 02896  
Contact: \_\_\_\_\_  
Project Location: **Haliwell Bldg #1 (was #1)**

Warwick, RI Phone# (401) 461-3993  
**ASBESTOS INSPECTION FORM**

Project Inspector: Kenneth Beliveau

Date: 12/30/05  
Type of Inspection: 6 month surveillance

|                | Suspect Material       | Approx. Amount | Friable | ACBM?   | No Damage | Phys. Damage |      | Accessible | Phys. Damage | Water Damage | Potential |          | Response Action | 6 month Surveillance |
|----------------|------------------------|----------------|---------|---------|-----------|--------------|------|------------|--------------|--------------|-----------|----------|-----------------|----------------------|
|                |                        |                |         |         |           | <10%         | >10% |            |              |              | Damage    | Sig. Dam |                 |                      |
| Boiler Room    | plaster walls/ceilings | 120 sf         |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                | flex duct              | 4 sf           |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                | doors                  | 1              | no      | assumed | x         |              |      | x          |              |              | x         |          | M7              | N                    |
|                |                        |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
| Exterior       | Transite ceiling       | 1,285 sf       | no      | yes     | x         |              |      | x          |              |              | x         |          | M7              | N                    |
|                | Transite siding        | 180 sf         | no      | yes     | x         |              |      | x          |              |              |           | x        | M4              | N                    |
|                | roof shingles          | 2,482 sf       | no      | assumed | x         |              |      |            |              |              |           |          | M8              | N                    |
|                | roof mastic            | 10 sf          | no      | assumed | x         |              |      |            |              |              |           |          | M8              | N                    |
|                | chimney sleeve         | 4 lf           | no      | assumed | x         |              |      |            |              |              |           |          | M8              | N                    |
|                |                        |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
| Above Ceilings | duct insulation        | 100 sf (est.)  | yes     | assumed | probable  |              |      |            | x            |              |           | x        | T5              | N                    |
|                |                        |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                |                        |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                |                        |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                |                        |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                |                        |                |         |         |           |              |      |            |              |              |           |          |                 |                      |

T=Thermal, S=Surfacing, M=Miscellaneous  
REM=Removed

6 Month Inspection; N=No Change, R=Repaired, D=Damaged,

P.O. BOX 772

Client: North Smithfield School Dept.  
Address: 450 Greenville Road  
North Smithfield, 02896

Warwick, RI Phone# (401) 461-3993  
ASBESTOS INSPECTION FORM

Project Inspector: Kenneth Beliveau

Contact:

Date: 12/30/05

Type of Inspection: 6 month surveillance

Halliwell Bldg #2 (was #2)

| Location            | Suspect Material     | Approx. Amount | Friable | ACBM?   | No Damage | Phys. Damage |      | Accessible | Phys. Damage | Water Damage | Potential |          | Response Action | 6 month Surveillance |
|---------------------|----------------------|----------------|---------|---------|-----------|--------------|------|------------|--------------|--------------|-----------|----------|-----------------|----------------------|
|                     |                      |                |         |         |           | <10%         | >10% |            |              |              | Damage    | Sig. Dam |                 |                      |
| Front Entrance Area | 1x1 CT large dot     |                |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                     | ceramic floor        | 66 sf          | no      | assumed | x         |              |      | x          |              |              |           |          | M8              | N                    |
|                     | window glazing       | 8 sf           | no      | yes     | x         |              |      | x          |              |              |           |          | M8              | N                    |
|                     | doors                | 1              | no      | assumed | x         |              |      | x          |              |              | x         |          | M7              | N                    |
| Left Classroom      |                      |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                     | 9x9 FT/A             | 825 sf         | no      | yes     | x         |              |      | x          |              |              | x         |          | M7              | N                    |
|                     | 2x4 CT fiss/pinhole  |                |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                     | 1x1 CT large dot     |                |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                     | counter top material | 50 sf          | no      | yes     | x         |              |      | x          |              |              | x         |          | M7              | N                    |
|                     | window glazing       | 8 sf           | no      | yes     | x         |              |      | x          |              |              |           |          | M8              | N                    |
|                     | chalk board          |                | no      | assumed | x         |              |      | x          |              |              |           |          | M8              | N                    |
|                     | caulk board          |                |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                     | doors                | 3              | no      | assumed | x         |              |      | x          |              |              | x         |          | M7              | N                    |
|                     |                      |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                     |                      |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                     |                      |                |         |         |           |              |      |            |              |              |           |          |                 |                      |

T=Thermal, S=Surfacing, M=Miscellaneous  
REM=Removed

6 Month Inspection; N=No Change, R=Repaired, D=Damaged,

MEI Environmental, Inc  
P.O. BC 772

Warwick, RI Phone# (401) 461-3993  
ASBESTOS INSPECTION FORM

Client: North Smithfield School Dept.  
Address: 450 Greenville Road  
North Smithfield, 02896

Project Inspector: Kenneth Beliveau

Date: 12/30/05  
Type of Inspection: 6 month surveillance

Contact:   
Project Location: Halliwell Bldg #2 (was #2)

|                 | Suspect Material     | Approx. Amount | Friable | ACBM?   | No Damage | Phys. Damage |      | Accessible | Phys. Damage | Water Damage | Potential |          | Response Action | 6 month Surveillance |
|-----------------|----------------------|----------------|---------|---------|-----------|--------------|------|------------|--------------|--------------|-----------|----------|-----------------|----------------------|
|                 |                      |                |         |         |           | <10%         | >10% |            |              |              | Damage    | Sig. Dam |                 |                      |
| Right Classroom | 9x9 FT/A             | 825 sf         | no      | yes     | x         |              |      | x          |              | x            |           |          | M7              | N                    |
|                 | 2x4 CT fiss/pinhole  |                |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                 | 1x1 CT large dot     |                |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                 | counter top material | 50 sf          | no      | yes     |           | 4 sf         |      | x          |              |              |           | x        | M3              | N                    |
|                 | window glazing       | 8 sf           | no      | yes     | x         |              |      | x          |              |              |           |          | M8              | N                    |
|                 | chalk board          |                | no      | assumed | x         |              |      | x          |              |              |           |          | M8              | N                    |
|                 | caulk board          |                |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                 | doors                | 3              | no      | assumed | x         |              |      | x          |              | x            |           |          | M7              | N                    |
|                 |                      |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
| Bathroom Area   | ceramic floor        | 148 sf         | no      | assumed | x         |              |      | x          |              |              |           |          | M8              | N                    |
|                 | 1x1 CT large dot     |                |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                 | window glazing       | 4sf            | no      | yes     | x         |              |      | x          |              |              |           |          | M8              | N                    |
|                 | partitions           | 60 sf          | no      | assumed | x         |              |      | x          |              |              | x         |          | M7              | N                    |
|                 | doors                | 6              | no      | assumed | x         |              |      | x          |              |              | x         |          | M7              | N                    |
|                 | 1x1 CT small dot     |                |         | no      |           |              |      |            |              |              |           |          |                 |                      |

T=Thermal, S=Surfacing, M=Miscellaneous  
REM=Removed

6 Month Inspection; N=No Change, R=Repaired, D=Damaged,



Client: North Smithfield School Dept.  
Address: 450 Greenville Road  
North Smithfield, 02896

Warwick, RI Phone# (401) 461-3993  
ASBESTOS INSPECTION FORM

Project Inspector:

Kenneth Beliveau

Contact:

Project Location:

Haliwell Bldg #2 (was #2)

Date: 12/30/05

Type of Inspection: 6 month surveillance

| Location       | Suspect Material       | Approx. Amount | Friable | ACBM?   | No Damage | Phys. Damage |      | Accessible | Phys. Damage | Water Damage | Potential |          | Response Action | 6 month Surveillance |
|----------------|------------------------|----------------|---------|---------|-----------|--------------|------|------------|--------------|--------------|-----------|----------|-----------------|----------------------|
|                |                        |                |         |         |           | <10%         | >10% |            |              |              | Damage    | Sig. Dam |                 |                      |
| Boiler Room    | plaster walls/ceilings | 120 sf         |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                | flex duct              | 4 sf           |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                | doors                  | 1              | no      | assumed | x         |              |      | x          |              | x            |           |          | M7              | N                    |
| Exterior       | Transite ceiling       | 1,285 sf       | no      | yes     | x         |              |      | x          |              |              |           | x        | M4              | N                    |
|                | Transite siding        | 180 sf         | no      | yes     | x         |              |      | x          |              | x            |           |          | M7              | N                    |
|                | roof shingles          | 2,482 sf       | no      | assumed | x         |              |      |            |              |              |           |          | M8              | N                    |
|                | roof mastic            | 10 sf          | no      | assumed | x         |              |      |            |              |              |           |          | M8              | N                    |
|                | chimney sleeve         | 4 lf           | no      | assumed | x         |              |      |            |              |              |           |          | M8              | N                    |
| Above Ceilings | duct insulation        | 100 sf (est.)  | yes     | assumed | probable  |              |      |            | x            |              |           | x        | T5              | N                    |
|                |                        |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                |                        |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                |                        |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                |                        |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                |                        |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                |                        |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                |                        |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                |                        |                |         |         |           |              |      |            |              |              |           |          |                 |                      |

T=Thermal, S=Surfacing, M=Miscellaneous  
REM=Removed

6 Month Inspection; N=No Change, R=Repaired, D=Damaged,

Client: North Smithfield School Dept.  
Address: 450 Greenville Road  
North Smithfield, 02896

Warwick, RI Phone# (401) 461-3993  
ASBESTOS INSPECTION FORM

Project Inspector: Kenneth Beliveau

Contact:   
Project Location: Halliwell Bldg #3 (was #3)

Date: 12/30/05  
Type of Inspection: 6 month surveillance

| Location            | Suspect Material     | Approx. Amount | Friable | ACBM?   | No Damage | Phys. Damage |      | Accessible | Phys. Damage | Water Damage | Potential |         | Response Action | 6 month Surveillance |
|---------------------|----------------------|----------------|---------|---------|-----------|--------------|------|------------|--------------|--------------|-----------|---------|-----------------|----------------------|
|                     |                      |                |         |         |           | <10%         | >10% |            |              |              | Damage    | Sig Dam |                 |                      |
| Front Entrance Area | 1x1 CT large dot     |                |         | no      |           |              |      |            |              |              |           |         |                 |                      |
|                     | ceramic floor        | 66 sf          | no      | assumed | x         |              |      | x          |              |              |           |         | M 8             | N                    |
|                     | window glazing       | 8 sf           | no      | yes     | x         |              |      | x          |              |              |           |         | M 8             | N                    |
|                     | doors                | 2              | no      | assumed | x         |              |      | x          |              |              | x         |         | M 7             | N                    |
|                     |                      |                |         |         |           |              |      |            |              |              |           |         |                 |                      |
| Left Classroom      | 9x9 FT/A             | 825 sf         | no      | yes     |           | 15 sf        |      | x          | x            |              | x         |         | M 3             | N                    |
|                     | 2x4 CT fiss/pinhole  |                |         | no      |           |              |      |            |              |              |           |         |                 |                      |
|                     | 1x1 CT large dot     |                |         | no      |           |              |      |            |              |              |           |         |                 |                      |
|                     | counter top material | 50 sf          | no      | yes     | x         |              |      | x          |              |              | x         |         | M 7             | N                    |
|                     | window glazing       | 8 sf           | no      | yes     | x         |              |      | x          |              |              |           |         | M 8             | N                    |
|                     | chalk board          |                | no      | assumed | x         |              |      | x          |              |              |           |         | M 8             | N                    |
|                     | caulk board          |                |         | no      |           |              |      |            |              |              |           |         |                 |                      |
|                     | doors                | 3              | no      | assumed | x         |              |      | x          |              |              | x         |         | M 7             | N                    |
|                     |                      |                |         |         |           |              |      |            |              |              |           |         |                 |                      |
|                     |                      |                |         |         |           |              |      |            |              |              |           |         |                 |                      |
|                     |                      |                |         |         |           |              |      |            |              |              |           |         |                 |                      |
|                     |                      |                |         |         |           |              |      |            |              |              |           |         |                 |                      |
|                     |                      |                |         |         |           |              |      |            |              |              |           |         |                 |                      |

T=Thermal, S=Surfacing, M=Miscellaneous  
REM=Removed

6 Month Inspection; N=No Change, R=Repaired, D=Damaged,

Client: North Smithfield School Dept.  
Address: 450 Greenville Road  
North Smithfield, 02896

Warwick, RI Phone# (401) 461-3993  
ASBESTOS INSPECTION FORM

Project Inspector:

Kenneth Beliveau

Contact:

Project Location

Halliwell Bldg #3 (was #3)

Date: 12/30/05

Type of Inspection: 6 month surveillance

| Location        | Suspect Material     | Approx. Amount | Friable | ACBM?   | No Damage | Phys. Damage |      | Accessible | Phys. Damage | Water Damage | Potential |         | Response Action | 6 month Surveillance |
|-----------------|----------------------|----------------|---------|---------|-----------|--------------|------|------------|--------------|--------------|-----------|---------|-----------------|----------------------|
|                 |                      |                |         |         |           | <10%         | >10% |            |              |              | Damage    | Sig.Dam |                 |                      |
| Right Classroom | 9x9 FT/A             | 825 sf         | no      | yes     |           | 7 sf         |      | x          | x            |              |           | x       | M3              | N                    |
|                 | 2x4 CT fiss/pinhole  |                |         | no      |           |              |      |            |              |              |           |         |                 |                      |
|                 | 1x1 CT large dot     |                |         | no      |           |              |      |            |              |              |           |         |                 |                      |
|                 | counter top material | 50 sf          | no      | yes     | x         |              |      | x          |              |              | x         |         | M7              | N                    |
|                 | window glazing       | 8 sf           | no      | yes     | x         |              |      | x          |              |              |           |         | M8              | N                    |
|                 | chalk board          |                | no      | assumed | x         |              |      | x          |              |              |           |         | M8              | N                    |
|                 | caulk board          |                |         | no      |           |              |      |            |              |              |           |         |                 |                      |
|                 | doors                | 3              | no      | assumed | x         |              |      | x          |              |              | x         |         | M7              | N                    |
|                 |                      |                |         |         |           |              |      |            |              |              |           |         |                 |                      |
| Bathroom Area   | ceramic floor        | 148 sf         | no      | assumed | x         |              |      | x          |              |              |           |         | M8              | N                    |
|                 | 2x2 CT fiss/pinhole  |                |         | no      |           |              |      |            |              |              |           |         |                 |                      |
|                 | window glazing       | 4sf            | no      | yes     | x         |              |      | x          |              |              |           |         | M8              | N                    |
|                 | partitions           | 60 sf          | no      | assumed | x         |              |      | x          |              |              | x         |         | M7              | N                    |
|                 | doors                | 6              | no      | assumed | x         |              |      | x          |              |              | x         |         | M7              | N                    |
|                 |                      |                |         |         |           |              |      |            |              |              |           |         |                 |                      |
|                 |                      |                |         |         |           |              |      |            |              |              |           |         |                 |                      |
|                 |                      |                |         |         |           |              |      |            |              |              |           |         |                 |                      |

T=Thermal, S=Surfacing, M=Miscellaneous  
REM=Removed

6 Month Inspection; N=No Change, R=Repaired, D=Damaged,

Client: North Smithfield School Dept.  
Address: 450 Greenville Road  
North Smithfield, 02896

Warwick, RI Phone# (401) 461-3993  
ASBESTOS INSPECTION FORM

Project Inspector:

Kenneth Beliveau

Date: 12/30/05  
Type of Inspection: 6 month surveillance

|                  |                            |
|------------------|----------------------------|
| Contact:         |                            |
| Project Location | Halliwell Bldg #3 (was #3) |

[illegible]

T=Thermal, S=Surfacing, M=Miscellaneous  
6 Month Inspection; N=No Change, R=Repaired, D=Damaged,  
REM=Removed



MEI Environmental, Inc  
P.O. B. 8772

Warwick, RI Phone# (401) 461-3993  
**ASBESTOS INSPECTION FORM**

Project Inspector: Kenneth Beliveau

Client: North Smithfield School Dept.  
Address: 450 Greenville Road  
North Smithfield, 02896

Contact: **Halliwell Bldg #4 (was #4)**  
Project Location

Date: 12/30/05  
Type of Inspection: 6 month surveillance

| Location            | Suspect Material     | Approx. Amount | Friable | ACBM?   | No Damage | Phys. Damage |      | Accessible | Phys. Damage | Water Damage | Potential |         | Response Action | 6 month Surveillance |
|---------------------|----------------------|----------------|---------|---------|-----------|--------------|------|------------|--------------|--------------|-----------|---------|-----------------|----------------------|
|                     |                      |                |         |         |           | <10%         | >10% |            |              |              | Damage    | Sig Dam |                 |                      |
| Front Entrance Area | 1x1 CT large dot     |                |         | no      |           |              |      |            |              |              |           |         |                 |                      |
|                     | ceramic floor        | 66 sf          | no      | assumed | x         |              |      | x          |              |              |           |         | M 8             | N                    |
|                     | window glazing       | 8 sf           | no      | yes     | x         |              |      | x          |              |              |           |         | M 8             | N                    |
|                     | doors                | 1              | no      | assumed | x         |              |      | x          |              | x            |           |         | M 7             | N                    |
| Left Classroom      |                      |                |         |         |           |              |      |            |              |              |           |         |                 |                      |
|                     | 9x9 FT/A             | 825 sf         | no      | yes     |           | 1 sf         |      | x          |              |              |           | x       | M 3             | N                    |
|                     | 2x4 CT fiss/pinhole  |                |         | no      |           |              |      |            |              |              |           |         |                 |                      |
|                     | 1x1 CT large dot     |                |         | no      |           |              |      |            |              |              |           |         |                 |                      |
|                     | counter top material | 50 sf          | no      | yes     | x         |              |      | x          |              |              | x         |         | M 7             | N                    |
|                     | window glazing       | 8 sf           | no      | yes     | x         |              |      | x          |              |              |           |         | M 8             | N                    |
|                     | chalk board          |                | no      | assumed | x         |              |      | x          |              |              |           |         | M 8             | N                    |
|                     | caulk board          |                |         | no      |           |              |      |            |              |              |           |         |                 |                      |
|                     | doors                | 4              | no      | assumed | x         |              |      | x          |              |              | x         |         | M 7             | N                    |
|                     |                      |                |         |         |           |              |      |            |              |              |           |         |                 |                      |
|                     |                      |                |         |         |           |              |      |            |              |              |           |         |                 |                      |
|                     |                      |                |         |         |           |              |      |            |              |              |           |         |                 |                      |

T=Thermal, S=Surfacing, M=Miscellaneous  
REM=Removed  
6 Month Inspection; N=No Change, R=Repaired, D=Damaged,

Contact: Haliwell Bldg #4 (was #4)  
Project Location:

Date: 12/30/05  
Type of Inspection: 6 month surveillance

| Location        | Suspect Material     | Approx. Amount | Friable | ACBM?   | No Damage | Phys. Damage |      | Accessible | Phys. Damage | Water Damage | Potential |          | Response Action | 6 month Surveillance |
|-----------------|----------------------|----------------|---------|---------|-----------|--------------|------|------------|--------------|--------------|-----------|----------|-----------------|----------------------|
|                 |                      |                |         |         |           | <10%         | >10% |            |              |              | Damage    | Sig. Dam |                 |                      |
| Right Classroom | 9x9 FT/A             | 825 sf         | no      | yes     | x         |              |      | x          |              |              | x         |          | M7              | N                    |
|                 | 2x4 CT fiss/pinhole  |                |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                 | 1x1 CT large dot     |                |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                 | counter top material | 50 sf          | no      | yes     | x         |              |      | x          |              |              | x         |          | M7              | N                    |
|                 | window glazing       | 8 sf           | no      | yes     | x         |              |      | x          |              |              |           |          | M8              | N                    |
|                 | chalk board          |                | no      | assumed | x         |              |      | x          |              |              |           |          | M8              | N                    |
|                 | caulk board          |                |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                 | doors                | 3              | no      | assumed | x         |              |      | x          |              |              | x         |          | M7              | N                    |
|                 |                      |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
| Bathroom Area   | blue sheet flooring  | 148 sf         | no      | assumed | x         |              |      | x          |              |              |           |          | M8              | N                    |
|                 | 2x2 CT fiss/pinhole  |                |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                 | window glazing       | 4sf            | no      | yes     | x         |              |      | x          |              |              |           |          | M8              | N                    |
|                 | partitions           | 60 sf          | no      | assumed | x         |              |      | x          |              |              | x         |          | M7              | N                    |
|                 | doors                | 4              | no      | assumed | x         |              |      | x          |              |              | x         |          | M7              | N                    |
|                 | ceramic floor        | 20 sf          | no      | assumed | x         |              |      | x          |              |              |           |          | M8              | N                    |
|                 | ceramic wall         | 128 sf         | no      | assumed | x         |              |      | x          |              |              |           |          | M8              | N                    |

T=Thermal, S=Surfacing, M=Miscellaneous  
REM=Removed  
6 Month Inspection; N=No Change, R=Repaired, D=Damaged,

Client: North Smithfield School Dept.  
Address: 450 Greenville Road  
North Smithfield

Project Inspector:

Kenneth Beliveau

Contact:

Project Location: Halliwel Bldg #4 (was #4)

Date:

12/30/05

Type of Inspection:

6 month surveillance

| Location       | Suspect Material       | Approx. Amount | Friable | ACBM?   | No Damage | Phys. Damage |      | Accessible | Phys. Damage | Water Damage | Potential |          | Response Action | 6 month Surveillance |
|----------------|------------------------|----------------|---------|---------|-----------|--------------|------|------------|--------------|--------------|-----------|----------|-----------------|----------------------|
|                |                        |                |         |         |           | <10%         | >10% |            |              |              | Damage    | Sig. Dam |                 |                      |
| Boiler Room    | plaster walls/ceilings | 120 sf         |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                | flex duct              | 4 sf           |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                | doors                  | 1              | no      | assumed | x         |              |      | x          |              |              | x         |          | M7              | N                    |
| Exterior       | Transite ceiling       | 1,285 sf       | no      | yes     | x         |              |      | x          |              |              |           | x        | M4              | N                    |
|                | Transite siding        | 180 sf         | no      | yes     | x         |              |      | x          |              |              | x         |          | M7              | N                    |
|                | roof shingles          | 2,900 sf       | no      | assumed | x         |              |      |            |              |              |           |          | M8              | N                    |
|                | roof mastic            | 10 sf          | no      | assumed | x         |              |      |            |              |              |           |          | M8              | N                    |
|                | chimney sleeve         | 4 lf           | no      | assumed | x         |              |      |            |              |              |           |          | M8              | N                    |
| Above Ceilings | duct insulation        | 100 sf (est.)  | yes     | assumed | probable  |              |      |            | x            |              |           | x        | T5              | N                    |
|                |                        |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                |                        |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                |                        |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                |                        |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                |                        |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                |                        |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                |                        |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                |                        |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                |                        |                |         |         |           |              |      |            |              |              |           |          |                 |                      |

T=Thermal, S=Surfacing, M=Miscellaneous  
REM=Removed

6 Month Inspection; N=No Change, R=Repaired, D=Damaged,

Client: North Smithfield School Dept.  
Address: 450 Greenville Road  
North Smithfield, 02896

Project Inspector:

Kenneth Beliveau

Contact:

Project Location: **Halliwell Bldg #7 (was #5)**

Date: 12/30/05

Type of Inspection: 6 month surveillance

| Location            | Suspect Material     | Approx. Amount | Friable | ACBM?   | No Damage | Phys. Damage |      | Accessible | Phys. Damage | Water Damage | Potential |         | Response Action | 6 month Surveillance |
|---------------------|----------------------|----------------|---------|---------|-----------|--------------|------|------------|--------------|--------------|-----------|---------|-----------------|----------------------|
|                     |                      |                |         |         |           | <10%         | >10% |            |              |              | Damage    | Sig Dam |                 |                      |
| Front Entrance Area | 1x1 CT large dot     |                |         | no      |           |              |      |            |              |              |           |         |                 |                      |
|                     | ceramic floor        | 66 sf          | no      | assumed | x         |              |      | x          |              |              |           |         | M8              | N                    |
|                     | window glazing       | 8 sf           | no      | yes     | x         |              |      | x          |              |              |           |         | M8              | N                    |
|                     | doors                | 1              | no      | assumed | x         |              |      | x          |              |              | x         |         | M7              | N                    |
|                     |                      |                |         |         |           |              |      |            |              |              |           |         |                 |                      |
| Left Classroom      | 9x9 FT/A             | 825 sf         | no      | yes     |           | 2 sf         |      | x          |              |              |           | x       | M3              | N                    |
|                     | 2x4 CT fiss/pinhole  |                |         | no      |           |              |      |            |              |              |           |         |                 |                      |
|                     | 1x1 CT large dot     |                |         | no      |           |              |      |            |              |              |           |         |                 |                      |
|                     | counter top material | 50 sf          | no      | yes     | x         |              |      | x          |              |              | x         |         | M7              | N                    |
|                     | window glazing       | 8 sf           | no      | yes     | x         |              |      | x          |              |              |           |         | M8              | N                    |
|                     | chalk board          |                | no      | assumed | x         |              |      | x          |              |              |           |         | M8              | N                    |
|                     | caulk board          |                |         | no      |           |              |      |            |              |              |           |         |                 |                      |
|                     | doors                | 3              | no      | assumed | x         |              |      | x          |              |              | x         |         | M7              | N                    |
|                     |                      |                |         |         |           |              |      |            |              |              |           |         |                 |                      |
|                     |                      |                |         |         |           |              |      |            |              |              |           |         |                 |                      |
|                     |                      |                |         |         |           |              |      |            |              |              |           |         |                 |                      |
|                     |                      |                |         |         |           |              |      |            |              |              |           |         |                 |                      |
|                     |                      |                |         |         |           |              |      |            |              |              |           |         |                 |                      |

T=Thermal, S=Surfacing, M=Miscellaneous  
REM=Removed

6 Month Inspection; N=No Change, R=Repaired, D=Damaged,



Client: North Smithfield School Dept.  
Address: 450 Greenville Road  
North Smithfield, 02896

Warwick, RI Phone# (401) 461-3993  
ASBESTOS INSPECTION FORM

Project Inspector:

Kenneth Beliveau

Client:

Project location:

Halliwell Bldg #7 (was #5)

Date: 12/30/05

Type of Inspection: 6 month surveillance

| Location        | Suspect Material     | Approx. Amount | Friable | ACBM?   | No Damage | Phys. Damage |      | Accessible | Phys. Damage | Water Damage | Potential |         | Response Action | 6 month Surveillance |
|-----------------|----------------------|----------------|---------|---------|-----------|--------------|------|------------|--------------|--------------|-----------|---------|-----------------|----------------------|
|                 |                      |                |         |         |           | <10%         | >10% |            |              |              | Damage    | Sig Dam |                 |                      |
| Right Classroom | 9x9 FT/A             | 825 sf         | no      | yes     | x         | 8 sf         |      | x          | x            |              | x         |         | M3              | N                    |
|                 | 2x4 CT fiss/pinhole  |                |         | no      |           |              |      |            |              |              |           |         |                 |                      |
|                 | 1x1 CT large dot     |                |         | no      |           |              |      |            |              |              |           |         |                 |                      |
|                 | counter top material | 50 sf          |         | yes     | x         |              |      | x          |              |              | x         |         | M7              | N                    |
|                 | window glazing       | 8 sf           |         | yes     | x         |              |      | x          |              |              |           |         | M8              | N                    |
|                 | chalk board          |                |         | assumed | x         |              |      | x          |              |              |           |         | M8              | N                    |
|                 | caulk board          |                |         | no      |           |              |      |            |              |              |           |         |                 |                      |
|                 | doors                | 3              |         | assumed | x         |              |      | x          |              |              | x         |         | M7              | N                    |
|                 |                      |                |         |         |           |              |      |            |              |              |           |         |                 |                      |
| Bathroom Area   | blue sheet flooring  | 148 sf         |         | assumed | x         |              |      | x          |              |              |           |         | M8              | N                    |
|                 | 2x4 CT fiss/pinhole  |                |         | no      |           |              |      |            |              |              |           |         |                 |                      |
|                 | window glazing       | 4sf            |         | yes     | x         |              |      | x          |              |              |           |         | M8              | N                    |
|                 | 1x1 CT large dot     |                |         | no      |           |              |      |            |              |              |           |         |                 |                      |
|                 | doors                | 6              |         | assumed | x         |              |      | x          |              |              | x         |         | M7              | N                    |
|                 | ceramic floor        | 20 sf          |         | assumed | x         |              |      | x          |              |              |           |         | M8              | N                    |
|                 | ceramic wall         | 128 sf         |         | assumed | x         |              |      | x          |              |              |           |         | M8              | N                    |

T=Thermal, S=Surfacing, M=Miscellaneous  
REM=Removed

6 Month Inspection; N=No Change, R=Repaired, D=Damaged,

Client: North Smithfield School Dept.  
Address: 450 Greenville Road  
North Smithfield, 02896

Warwick, RI Phone# (401) 461-3993  
ASBESTOS INSPECTION FORM

Project Inspector:

Kenneth Beliveau

Client:

Project Location:

Halliwell Bldg #7 (was #5)

Date: 12/30/05

Type of Inspection: 6 month surveillance

| Location       | Suspect Material       | Approx. Amount | Friable | ACBM?   | No Damage | Phys. Damage |      | Accessible | Phys. Damage | Water Damage | Potential |         | Response Action | 6 month Surveillance |
|----------------|------------------------|----------------|---------|---------|-----------|--------------|------|------------|--------------|--------------|-----------|---------|-----------------|----------------------|
|                |                        |                |         |         |           | <10%         | >10% |            |              |              | Damage    | Sig.Dam |                 |                      |
| Boiler Room    | plaster walls/ceilings | 120 sf         |         | no      |           |              |      |            |              |              |           |         |                 |                      |
|                | flex duct              | 4 sf           |         | no      |           |              |      |            |              |              |           |         |                 |                      |
|                | doors                  | 1              | no      | assumed | x         |              |      | x          |              |              | x         |         | M7              | N                    |
| Exterior       | Transite ceiling       | 1,285 sf       | no      | yes     | x         |              |      | x          |              |              |           | x       | M4              | N                    |
|                | Transite siding        | 180 sf         | no      | yes     | x         |              |      | x          |              |              | x         |         | M7              | N                    |
|                | roof shingles          | 2,900 sf       | no      | assumed | x         |              |      |            |              |              |           |         | M8              | N                    |
|                | roof mastic            | 10 sf          | no      | assumed | x         |              |      |            |              |              |           |         | M8              | N                    |
|                | chimney sleeve         | 4 lf           | no      | assumed | x         |              |      |            |              |              |           |         | M8              | N                    |
| Above Ceilings | duct insulation        | 100 sf (est.)  | yes     | assumed | probable  |              |      |            | x            |              |           | x       | T5              | N                    |
|                |                        |                |         |         |           |              |      |            |              |              |           |         |                 |                      |
|                |                        |                |         |         |           |              |      |            |              |              |           |         |                 |                      |
|                |                        |                |         |         |           |              |      |            |              |              |           |         |                 |                      |
|                |                        |                |         |         |           |              |      |            |              |              |           |         |                 |                      |
|                |                        |                |         |         |           |              |      |            |              |              |           |         |                 |                      |
|                |                        |                |         |         |           |              |      |            |              |              |           |         |                 |                      |
|                |                        |                |         |         |           |              |      |            |              |              |           |         |                 |                      |
|                |                        |                |         |         |           |              |      |            |              |              |           |         |                 |                      |

T=Thermal, S=Surfacing, M=Miscellaneous  
REM=Removed

6 Month Inspection; N=No Change, R=Repaired, D=Damaged,

Client: North Smithfield School Dept.  
Address: 450 Greenville Road  
North Smithfield, 02896

Warwick, RI Phone# (401) 461-3993  
**ASBESTOS INSPECTION FORM**

Project Inspector:

Kenneth Beliveau

Contact:

Project Location **Haliwell Bldg #8 (was #7)**

Date: 12/30/05

Type of Inspection: 6 month surveillance

| Location            | Suspect Material         | Approx. Amount | Friable | ACBM?   | No Damage | Phys. Damage |      | Accessible | Phys. Damage | Water Damage | Potential |          | Response Action | 6 month Surveillance |
|---------------------|--------------------------|----------------|---------|---------|-----------|--------------|------|------------|--------------|--------------|-----------|----------|-----------------|----------------------|
|                     |                          |                |         |         |           | <10%         | >10% |            |              |              | Damage    | Sig. Dam |                 |                      |
| Front Entrance Area | 1x1 CT large dot         |                |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                     | ceramic floor            | 66 sf          | no      | assumed | x         |              |      | x          |              |              |           |          | M 8             | N                    |
|                     | window glazing           | 8 sf           | no      | yes     | x         |              |      | x          |              |              |           |          | M 8             | N                    |
|                     | doors                    | 1              | no      | assumed | x         |              |      | x          |              | x            |           |          | M 7             | N                    |
|                     | 1x1 CT small dot         |                |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                     |                          |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                     |                          |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                     |                          |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
| Left Classroom      | 9x9 FT/A                 | 825 sf         | no      | yes     |           | 6 sf         |      | x          | x            |              |           | x        | M 3             | N                    |
|                     | 2x4 CT fiss/pinhole      |                |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                     | 1x1 CT large dot         |                |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                     | counter top material     | 50 sf          | no      | yes     | x         |              |      | x          |              | x            |           |          | M 7             | N                    |
|                     | window glazing           | 8 sf           | no      | yes     | x         |              |      | x          |              |              |           |          | M 8             | N                    |
|                     | chalk board              |                | no      | assumed | x         |              |      | x          |              |              |           |          | M 8             | N                    |
|                     | caulk board              |                |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                     | doors                    | 3              | no      | assumed | x         |              |      | x          |              |              | x         |          | M 7             | N                    |
|                     | perforated cabinet board |                |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                     |                          |                |         |         |           |              |      |            |              |              |           |          |                 |                      |

T=Thermal, S=Surfacing, M=Miscellaneous  
REM=Removed

6 Month Inspection; N=No Change, R=Repaired, D=Damaged,

Client: North Smithfield School Dept.  
Address: 450 Greenville Road  
North Smithfield, 02896

Warwick, RI Phone# (401) 461-3993  
ASBESTOS INSPECTION FORM

Project Inspector:

Kenneth Beliveau

Contact:

Haliwell Bldg #8 (was #7)

Date: 12/30/05

Type of Inspection: 6 month surveillance

|                 | Suspect Material     | Approx. Amount | Friable | ACBM?   | No Damage | Phys. Damage |      | Accessible | Phys. Damage | Water Damage | Potential |          | Response Action | 6 month Surveillance |
|-----------------|----------------------|----------------|---------|---------|-----------|--------------|------|------------|--------------|--------------|-----------|----------|-----------------|----------------------|
|                 |                      |                |         |         |           | <10%         | >10% |            |              |              | Damage    | Sig. Dam |                 |                      |
| Right Classroom | 9x9 FT/A             | 825 sf         | no      | yes     |           | 10sf         |      | x          | x            |              |           | x        | M3              | N                    |
|                 | 2x4 CT fiss/pinhole  |                |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                 | 1x1 CT large dot     |                |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                 | counter top material | 70 sf          | no      | yes     | x         |              |      | x          |              |              |           |          | M7              | N                    |
|                 | window glazing       | 8 sf           | no      | yes     | x         |              |      | x          |              |              |           |          | M8              | N                    |
|                 | chalk board          |                | no      | assumed | x         |              |      | x          |              |              |           |          | M8              | N                    |
|                 | caulk board          |                |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                 | doors                | 3              | no      | assumed | x         |              |      | x          |              |              | x         |          | M7              | N                    |
|                 |                      |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
| Bathroom Area   | blue sheet flooring  | 132 sf         | no      | assumed | x         |              |      | x          |              |              | x         |          | M7              | N                    |
|                 | 2x2 CT fiss/pinhole  |                |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                 | window glazing       | 4sf            | no      | yes     | x         |              |      | x          |              |              |           |          | M8              | N                    |
|                 | doors                | 6              | no      | assumed | x         |              |      | x          |              |              | x         |          | M7              | N                    |
|                 | ceramic floor        | 16 sf          | no      | assumed | x         |              |      | x          |              |              |           |          | M8              | N                    |
|                 | ceramic wall         | 128 sf         | no      | assumed | x         |              |      | x          |              |              |           |          | M8              | N                    |
|                 |                      |                |         |         |           |              |      |            |              |              |           |          |                 |                      |

T=Thermal, S=Surfacing, M=Miscellaneous  
REM=Removed

6 Month Inspection; N=No Change, R=Repaired, D=Damaged,



MEI Environmental, Inc  
P.O. Box 3772

Warwick, RI Phone# (401) 461-3993  
**ASBESTOS INSPECTION FORM**

Client: North Smithfield School Dept.  
Address: 450 Greenville Road  
North Smithfield, 02896

Project Inspector:

Kenneth Beliveau

Contact:

Date: 12/30/05

Type of Inspection: 6 month surveillance

**Halliwell Bldg #8 (was #7)**

| Location       | Suspect Material       | Approx. Amount | Friable | ACBM?   | No Damage | Phys. Damage |      | Accessible | Phys. Damage | Water Damage | Potential |         | Response Action | 6 month Surveillance |
|----------------|------------------------|----------------|---------|---------|-----------|--------------|------|------------|--------------|--------------|-----------|---------|-----------------|----------------------|
|                |                        |                |         |         |           | <10%         | >10% |            |              |              | Damage    | Sig.Dam |                 |                      |
| Boiler Room    | plaster walls/ceilings | 120 sf         |         | no      |           |              |      |            |              |              |           |         |                 |                      |
|                | flex duct              | 4 sf           |         | no      |           |              |      |            |              |              |           |         |                 |                      |
|                | doors                  | 1              | no      | assumed | x         |              |      | x          |              |              | x         |         | M7              | N                    |
| Exterior       |                        |                |         |         |           |              |      |            |              |              |           |         |                 |                      |
|                | Transite ceiling       | 1,285 sf       | no      | yes     | x         |              |      | x          |              |              |           | x       | M4              | N                    |
|                | Transite siding        | 180 sf         | no      | yes     | x         |              |      | x          |              |              | x         |         | M7              | N                    |
|                | roof shingles          | 2,900 sf       | no      | assumed | x         |              |      |            |              |              |           |         | M8              | N                    |
|                | roof mastic            | 10 sf          | no      | assumed | x         |              |      |            |              |              |           |         | M8              | N                    |
|                | chimney sleeve         | 4 lf           | no      | assumed | x         |              |      |            |              |              |           |         | M8              | N                    |
|                |                        |                |         |         |           |              |      |            |              |              |           |         |                 |                      |
| Above Ceilings | duct insulation        | 100 sf (est.)  | yes     | assumed | probable  |              |      |            | x            |              |           | x       | T5              | N                    |
|                |                        |                |         |         |           |              |      |            |              |              |           |         |                 |                      |
|                |                        |                |         |         |           |              |      |            |              |              |           |         |                 |                      |
|                |                        |                |         |         |           |              |      |            |              |              |           |         |                 |                      |
|                |                        |                |         |         |           |              |      |            |              |              |           |         |                 |                      |
|                |                        |                |         |         |           |              |      |            |              |              |           |         |                 |                      |
|                |                        |                |         |         |           |              |      |            |              |              |           |         |                 |                      |
|                |                        |                |         |         |           |              |      |            |              |              |           |         |                 |                      |

T=Thermal, S=Surfacing, M=Miscellaneous  
REM=Removed  
6 Month Inspection; N=No Change, R=Repaired, D=Damaged,

Client: North Smithfield School Dept.  
Address: 450 Greenville Road  
North Smithfield, 02896

Warwick, RI Phone# (401) 461-3993  
ASBESTOS INSPECTION FORM

Project Inspector:

Kenneth Beliveau

Contact:

Project Location:

Halliwel Bldg #11 (was #9)

Date: 12/30/05

Type of Inspection: 6 month surveillance

| Location            | Suspect Material     | Approx. Amount | Friable | ACBM?   | No Damage | Phys. Damage |      | Accessible | Phys. Damage | Water Damage | Potential |         | Response Action | 6 month Surveillance |
|---------------------|----------------------|----------------|---------|---------|-----------|--------------|------|------------|--------------|--------------|-----------|---------|-----------------|----------------------|
|                     |                      |                |         |         |           | <10%         | >10% |            |              |              | Damage    | Sig.Dam |                 |                      |
| Front Entrance Area | 1x1 CT large dot     |                |         | no      |           |              |      |            |              |              |           |         |                 |                      |
|                     | ceramic floor        | 66 sf          | no      | assumed | x         |              |      | x          |              |              |           |         | M 8             | N                    |
|                     | window glazing       | 8 sf           | no      | yes     | x         |              |      | x          |              |              |           |         | M 8             | N                    |
|                     | doors                | 1              | no      | assumed | x         |              |      | x          |              |              | x         |         | M 7             | N                    |
|                     |                      |                |         |         |           |              |      |            |              |              |           |         |                 |                      |
|                     |                      |                |         |         |           |              |      |            |              |              |           |         |                 |                      |
|                     |                      |                |         |         |           |              |      |            |              |              |           |         |                 |                      |
| Left Classroom      | 9x9 FT/A             | 825 sf         | no      | yes     |           | 4 sf         |      | x          | x            |              |           | x       | M 3             | N                    |
|                     | 2x4 CT fiss/pinhole  |                |         | no      |           |              |      |            |              |              |           |         |                 |                      |
|                     | 1x1 CT large dot     |                |         | no      |           |              |      |            |              |              |           |         |                 |                      |
|                     | counter top material | 50 sf          | no      | yes     | x         |              |      | x          |              |              | x         |         | M 7             | N                    |
|                     | window glazing       | 8 sf           | no      | yes     | x         |              |      | x          |              |              |           |         | M 8             | N                    |
|                     | chalk board          |                | no      | assumed | x         |              |      | x          |              |              |           |         | M 8             | N                    |
|                     | caulk board          |                |         | no      |           |              |      |            |              |              |           |         |                 |                      |
|                     | doors                | 3              | no      | assumed | x         |              |      | x          |              |              | x         |         | M 7             | N                    |
|                     |                      |                |         |         |           |              |      |            |              |              |           |         |                 |                      |
|                     |                      |                |         |         |           |              |      |            |              |              |           |         |                 |                      |
|                     |                      |                |         |         |           |              |      |            |              |              |           |         |                 |                      |

T=Thermal, S=Surfacing, M=Miscellaneous  
REM=Removed

6 Month Inspection; N=No Change, R=Repaired, D=Damaged,

MEI Environmental, Inc  
P.O. Box 3772  
Warwick, RI Phone# (401) 461-3993  
ASBESTOS INSPECTION FORM

Client: North Smithfield School Dept.  
Address: 450 Greenville Road  
North Smithfield, 02896

Project Inspector: Kenneth Beliveau

Contact:   
Project location: **Halliwell Bldg #11 (was #9)**

Date: 12/30/05  
Type of Inspection: 6 month surveillance

| Location        | Suspect Material     | Approx. Amount | Friable | ACBM?   | No Damage | Phys. Damage |      | Accessible | Phys. Damage | Water Damage | Potential |         | Response Action | 6 month Surveillance |
|-----------------|----------------------|----------------|---------|---------|-----------|--------------|------|------------|--------------|--------------|-----------|---------|-----------------|----------------------|
|                 |                      |                |         |         |           | <10%         | >10% |            |              |              | Damage    | Sig Dam |                 |                      |
| Right Classroom | 9x9 FT/A             | 825 sf         | no      | yes     | x         | 3 sf         |      | x          | x            |              | x         |         | M3              | N                    |
|                 | 2x4 CT fiss/pinhole  |                |         | no      |           |              |      |            |              |              |           |         |                 |                      |
|                 | 1x1 CT large dot     |                |         | no      |           |              |      |            |              |              |           |         |                 |                      |
|                 | counter top material | 100 sf         | no      | yes     |           | 5 sf         |      | x          | x            |              |           | x       | M3              | N                    |
|                 | window glazing       | 8 sf           | no      | yes     | x         |              |      | x          |              |              |           |         | M8              | N                    |
|                 | chalk board          |                | no      | assumed | x         |              |      | x          |              |              |           |         | M8              | N                    |
|                 | caulk board          |                |         | no      |           |              |      |            |              |              |           |         |                 |                      |
|                 | doors                | 3              | no      | assumed | x         |              |      | x          |              |              | x         |         | M7              | N                    |
|                 |                      |                |         |         |           |              |      |            |              |              |           |         |                 |                      |
| Bathroom Area   | 1x1 CT large dot     |                |         | no      |           |              |      |            |              |              |           |         |                 |                      |
|                 | window glazing       | 4sf            | no      | yes     | x         |              |      | x          |              |              |           |         | M8              | N                    |
|                 | doors                | 6              | no      | assumed | x         |              |      | x          |              |              | x         |         | M7              | N                    |
|                 | ceramic floor        | 16 sf          | no      | assumed | x         |              |      | x          |              |              |           |         | M8              | N                    |
|                 |                      |                |         |         |           |              |      |            |              |              |           |         |                 |                      |
|                 |                      |                |         |         |           |              |      |            |              |              |           |         |                 |                      |
|                 |                      |                |         |         |           |              |      |            |              |              |           |         |                 |                      |
|                 |                      |                |         |         |           |              |      |            |              |              |           |         |                 |                      |
|                 |                      |                |         |         |           |              |      |            |              |              |           |         |                 |                      |

T=Thermal, S=Surfacing, M=Miscellaneous  
REM=Removed  
6 Month Inspection; N=No Change, R=Repaired, D=Damaged,

Client:

Address:

North Smithfield School Dept.  
450 Greenville Road  
North Smithfield, 02896

Warwick, RI Phone# (401) 461-3993  
ASBESTOS INSPECTION FORM

Project Inspector:

Kenneth Beliveau

**Contact:**

Project Location:

Halliwell Bldg #11 (was #9)

Date: 12/30/05

Type of Inspection: 6 month surveillance

[illegible]

T=Thermal, S=Surfacing, M=Miscellaneous  
REM=Removed

6 Month Inspection; N=No Change, R=Repaired, D=Damaged,



Client:

Address:

North Smithfield School Dept.

450 Greenville Road

North Smithfield, 02896

Contact:

Project Location:

**Halliwell Bldg #6 (was #6)**

Warwick, RI Phone# (401) 461-3993

# ASBESTOS INSPECTION FORM

Project Inspector:

Kenneth Beliveau

Date: 12/30/05

Type of Inspection:

[illegible]

T=Thermal, S=Surfacing, M=Miscellaneous  
REM=Removed

6 Month Inspection; N=No Change, R=Repaired, D=Damaged,

Client: North Smithfield School Dept.  
Address: 450 Greenville Road  
North Smithfield, 02896

Warwick, RI Phone# (401) 461-3993  
ASBESTOS INSPECTION FORM

Project Inspector:

Kenneth Beliveau

Contact:

Project Location: Halliwell Bldg #6 (was #6)

Date: 12/30/05

Type of Inspection: 6 month surveillance

| Location                           | Suspect Material | Approx. Amount | Friable | ACBM?   | No Damage | Phys. Damage |      | Accessible | Phys. Damage | Water Damage | Potential |          | Response Action | 6 month Surveillance |
|------------------------------------|------------------|----------------|---------|---------|-----------|--------------|------|------------|--------------|--------------|-----------|----------|-----------------|----------------------|
|                                    |                  |                |         |         |           | <10%         | >10% |            |              |              | Damage    | Sig. Dam |                 |                      |
| Front Entrance Area                | 1x1 CT large dot |                |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                                    | ceramic floor    | 66 sf          | no      | assumed | x         |              |      | x          |              |              |           |          | M 8             | N                    |
|                                    | window glazing   | 8 sf           | no      | yes     | x         |              |      | x          |              |              |           |          | M 8             | N                    |
|                                    | doors            | 1              | no      | assumed | x         |              |      | x          |              |              | x         |          | M 7             | N                    |
|                                    |                  |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                                    |                  |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                                    |                  |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
| Administrative Offices (left side) | 9x9 FT/A         |                |         |         |           |              |      |            |              |              |           |          |                 | REM                  |
|                                    | doors            | 5              | no      | assumed | x         |              |      | x          |              |              | x         |          | M 7             | N                    |
|                                    | 1x1 CT large dot |                |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                                    | window glazing   | 8sf            | no      | yes     | x         |              |      | x          |              |              |           |          | M 8             | N                    |
| (Teacher's room)                   | 9X9 FT/A         | 200 sf         | no      | yes     | x         |              |      | x          |              |              |           |          | M7              | N                    |
|                                    |                  |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                                    |                  |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                                    |                  |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                                    |                  |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                                    |                  |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                                    |                  |                |         |         |           |              |      |            |              |              |           |          |                 |                      |

T=Thermal, S=Surfacing, M=Miscellaneous  
REM=Removed

6 Month Inspection; N=No Change, R=Repaired, D=Damaged,

Client: North Smithfield School Dept.  
Address: 450 Greenville Road  
North Smithfield, 02896

Warwick, RI Phone# (401) 461-3993  
ASBESTOS INSPECTION FORM

Project Inspector:

Kenneth Beliveau

Contact:

Project Location: Halliwell Bldg #6 (was #6)

Date: 12/30/05

Type of Inspection: 6 month surveillance

| Location       | Suspect Material       | Approx. Amount | Friable | ACBM?   | No Damage | Phys. Damage |      | Accessible | Phys. Damage | Water Damage | Potential |          | Response Action | 6 month Surveillance |
|----------------|------------------------|----------------|---------|---------|-----------|--------------|------|------------|--------------|--------------|-----------|----------|-----------------|----------------------|
|                |                        |                |         |         |           | <10%         | >10% |            |              |              | Damage    | Sig. Dam |                 |                      |
| Boiler Room    | plaster walls/ceilings | 210 sf         |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                | flex duct              | 4 sf           |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                | doors                  | 1              | no      | assumed | x         |              |      | x          |              |              | x         |          | M7              | N                    |
| Exterior       | Transite ceiling       | 1,285 sf       | no      | yes     |           | 4 sf         |      | x          | x            |              |           | x        | M3              | N                    |
|                | Transite siding        | 180 sf         | no      | yes     | x         |              |      | x          |              |              | x         |          | M7              | N                    |
|                | roof shingles          | 2,900 sf       | no      | assumed | x         |              |      |            |              |              |           |          | M8              | N                    |
|                | roof mastic            | 10 sf          | no      | assumed | x         |              |      |            |              |              |           |          | M8              | N                    |
|                | chimney sleeve         | 4 lf           | no      | assumed | x         |              |      |            |              |              |           |          | M8              | N                    |
| Above Ceilings | duct insulation        | 100 sf (est.)  | yes     | assumed | probable  |              |      |            | x            |              |           | x        | T5              | N                    |
|                |                        |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                |                        |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                |                        |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                |                        |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                |                        |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                |                        |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                |                        |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                |                        |                |         |         |           |              |      |            |              |              |           |          |                 |                      |

T=Thermal, S=Surfacing, M=Miscellaneous  
REM=Removed

6 Month Inspection; N=No Change, R=Repaired, D=Damaged,

MEI Environmental, Inc  
P.O. Box 3772

Client: North Smithfield School Dept.  
Address: 450 Greenville Road  
North Smithfield, 02896

Warwick, RI Phone# (401) 461-3993  
ASBESTOS INSPECTION FORM

Project Inspector:

Kenneth Beliveau

Contact:

Project Location: **Halliwell Bldg #5 (was #11 A/B)**

Date: 12/30/05

Type of Inspection: 6 month surveillance

| Location                               | Suspect Material     | Approx. Amount | Friable | ACBM?   | No Damage | Phys. Damage |      | Accessible | Phys. Damage | Water Damage | Potential |          | Response Action | 6 month Surveillance |
|----------------------------------------|----------------------|----------------|---------|---------|-----------|--------------|------|------------|--------------|--------------|-----------|----------|-----------------|----------------------|
|                                        |                      |                |         |         |           | <10%         | >10% |            |              |              | Damage    | Sig. Dam |                 |                      |
| Front Entrance Area (including closet) | 1x1 CT large dot     |                |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                                        | ceramic floor        | 66 sf          | no      | assumed | x         |              |      | x          |              |              |           |          | M 8             | N                    |
|                                        | window glazing       | 8 sf           | no      | yes     | x         |              |      | x          |              |              |           |          | M 8             | N                    |
|                                        | doors                | 1              | no      | assumed | x         |              |      | x          |              | x            |           |          | M 7             | N                    |
|                                        | 9x9 Flooring         | 20 sf          | no      | tes     | x         |              |      | x          |              |              |           |          | M 8             | N                    |
|                                        |                      |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                                        | 9x9 FT/A             | 825 sf         | no      | yes     | x         |              |      | x          |              | x            |           |          | M 7             | N                    |
|                                        | 2x4 CT fiss/pinhole  |                |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                                        | 1x1 CT large dot     |                |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                                        | counter top material | 50 sf          | no      | yes     |           | 1 sf         |      | x          |              | x            |           | x        | M 3             | N                    |
|                                        | window glazing       | 8 sf           | no      | yes     | x         |              |      | x          |              |              |           |          | M 8             | N                    |
|                                        | chalk board          |                | no      | assumed | x         |              |      | x          |              |              |           |          | M 8             | N                    |
|                                        | caulk board          |                |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                                        | doors                | 3              | no      | assumed | x         |              |      | x          |              | x            |           |          | M 7             | N                    |
|                                        |                      |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                                        |                      |                |         |         |           |              |      |            |              |              |           |          |                 |                      |

T=Thermal, S=Surfacing, M=Miscellaneous  
REM=Removed

6 Month Inspection; N=No Change, R=Repaired, D=Damaged,



MEI Environmental, Inc  
P.O. Box 772  
Warwick, RI Phone# (401) 461-3993

North Smithfield School Dept.  
450 Greenville Road  
North Smithfield, 02896

Client:  
Address:  
Contact:

Project Inspector:  
Kenneth Beliveau

Date: 12/30/05  
Type of Inspection: 6 month surveillance

Halliwel Bldg #5 (was #11 A/B)

Project Location:

| Location                            | Suspect Material | Approx. Amount | Friable | ACBM?   | No Damage | Phys. Damage |      | Accessible | Phys. Damage | Water Damage | Potential |          | Response Action | 6 month Surveillance |
|-------------------------------------|------------------|----------------|---------|---------|-----------|--------------|------|------------|--------------|--------------|-----------|----------|-----------------|----------------------|
|                                     |                  |                |         |         |           | <10%         | >10% |            |              |              | Damage    | Sig. Dam |                 |                      |
| Right Classroom                     | 9x9 FT/A         | 825 sf         | no      | yes     |           | 10 sf        |      | x          |              | x            | x         |          | M3              | N                    |
|                                     | 2x4 CT           |                |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                                     | flss/pinhole     |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                                     | 1x1 CT           |                |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                                     | large dot        |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                                     | window glazing   | 8 sf           | no      | yes     | x         |              |      | x          |              |              |           |          | M8              | N                    |
|                                     | chalk board      |                | no      | assumed | x         |              |      | x          |              |              |           |          | M8              | N                    |
|                                     | caulk board      |                |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                                     | doors            | 3              | no      | assumed | x         |              |      | x          |              | x            |           |          | M7              | N                    |
|                                     |                  |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                                     |                  |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                                     |                  |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
| Bathroom Area (Library-R Classroom) | 1x1 CT large dot |                |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                                     | doors            | 6              | no      | assumed | x         |              |      | x          |              | x            |           |          | M7              | N                    |
|                                     | ceramic floor    | 142 sf         | no      | assumed | x         |              |      | x          |              |              |           |          | M8              | N                    |
|                                     |                  |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
| Above Ceilings                      | duct insulation  | 100 sf (est.)  | yes     | assumed | probable  |              |      |            | x            |              |           | x        | T5              | N                    |
|                                     |                  |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                                     |                  |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                                     |                  |                |         |         |           |              |      |            |              |              |           |          |                 |                      |

T=Thermal, S=Surfacing, M=Miscellaneous  
REM=Removed  
6 Month Inspection; N=No Change, R=Repaired, D=Damaged,

MEI Environmental, Inc  
P.O. Box 772  
Warwick, RI Phone# (401) 461-3993  
ASBESTOS INSPECTION FORM

Client: North Smithfield School Dept.  
Address: 450 Greenville Road  
North Smithfield, 02896

Project Inspector: Kenneth Beliveau

Client: Haliwell Bldg #5 (was #11 A/B)  
Project Location:

Date: 12/30/05  
Type of Inspection: 6 Month Surveillance

| Location              | Suspect Material       | Approx. Amount | Friable | ACBM?   | No Damage | Phys. Damage |      | Accessible | Phys. Damage | Water Damage | Potential |          | Response Action | 6 month Surveillance |
|-----------------------|------------------------|----------------|---------|---------|-----------|--------------|------|------------|--------------|--------------|-----------|----------|-----------------|----------------------|
|                       |                        |                |         |         |           | <10%         | >10% |            |              |              | Damage    | Sig. Dam |                 |                      |
| Boiler Room           | plaster walls/ceilings | 240 sf         |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                       | flex duct              | 4 sf           |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                       | doors                  | 1              | no      | assumed | x         |              |      | x          |              |              | x         |          | M7              | N                    |
| Exterior              | Transite ceiling       | 1,860 sf       | no      | yes     | x         |              |      | x          |              |              | x         |          | M7              | N                    |
|                       | Transite siding        | 342 sf         | no      | yes     | x         |              |      | x          |              |              | x         |          | M7              | N                    |
|                       | roof shingles          | 5,246 sf       | no      | assumed | x         |              |      |            |              |              |           |          | M8              | N                    |
|                       | roof mastic            | 10 sf          | no      | assumed | x         |              |      |            |              |              |           |          | M8              | N                    |
|                       | chimney sleeve         | 4 lf           | no      | assumed | x         |              |      |            |              |              |           |          | M8              | N                    |
| Front Entrance Closet | 9x9 FT/A               | 26 sf          | no      | yes     | x         |              |      | x          |              |              | x         |          | M7              | N                    |
|                       | 1x1 CT large dot       |                |         | no      |           |              |      |            |              |              |           |          | ---             |                      |
|                       | 1x1 CT small dot       |                |         | no      |           |              |      |            |              |              |           |          | ---             |                      |
|                       | doors                  | 1              | no      | assumed | x         |              |      | x          |              |              | x         |          | M7              | N                    |
|                       |                        |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                       |                        |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                       |                        |                |         |         |           |              |      |            |              |              |           |          |                 |                      |

T=Thermal, S=Surfacing, M=Miscellaneous  
REM=Removed  
6 Month Inspection; N=No Change, R=Repaired, D=Damaged,

Project Inspector: Kenneth Belliveau  
 Date: 12/30/05  
 Type of Inspection: 6 month surveillance

Warwick, RI Phone# (401) 461-3993  
ASBESTOS INSPECTION FORM

Halliwell Bldg #5 (was #11 A/B)

[illegible]

T=Thermal, S=Surfacing, M=Miscellaneous  
REM=Removed

P.O. BC 772

Client: North Smithfield School Dept.

Warwick, RI Phone# (401) 461-3993

Project Inspector: Kenneth Beliveau

Address: 450 Greenville Road

ASBESTOS INSPECTION FORM

North Smithfield, 02896

Contact:

Date: 12/30/05

Project Location: Halliwell Bldg #9 (was #10)

Type of Inspection: 6 month surveillance

| Location             | Suspect Material    | Approx. Amount | Friable | ACBM?   | No Damage | Phys. Damage |      | Accessible   | Phys. Damage | Water Damage | Potential |          | Response Action | 6 month Surveillance |
|----------------------|---------------------|----------------|---------|---------|-----------|--------------|------|--------------|--------------|--------------|-----------|----------|-----------------|----------------------|
|                      |                     |                |         |         |           | <10%         | >10% |              |              |              | Damage    | Sig. Dam |                 |                      |
| Basement             | 12x12 FT/A          |                |         | no      |           |              |      |              |              |              |           |          |                 |                      |
|                      | 9x9 FT/A            | 1820 sf        | no      | assumed | x         |              |      | under carpet |              |              |           |          | M:8             | N                    |
|                      | 2x2 CT HM/pinhole   |                |         | no      |           |              |      |              |              |              |           |          |                 |                      |
|                      | ceramic floor       | 40 sf          | no      | assumed | x         |              |      | x            |              |              |           |          | M:8             | N                    |
|                      | window glazing      | 18 sf          | no      | yes     | x         |              |      | x            |              |              |           |          | M:8             | N                    |
|                      | Transite siding     | 150 sf         | no      | yes     | x         |              |      | x            |              | x            |           |          | M:7             | N                    |
|                      | grey base molding   |                |         | no      |           |              |      |              |              |              |           |          |                 |                      |
|                      | chalk board         |                | no      | assumed | x         |              |      | x            |              |              |           |          | M:8             | N                    |
|                      | caulk board         |                |         | no      |           |              |      |              |              |              |           |          |                 |                      |
|                      | tar wrap insulation | 12 lf          | no      | yes     |           | 2 lf         |      | x            | x            |              |           | x        | M:3             | N                    |
| Basement Boiler Room | concrete wall       |                |         | no      |           |              |      |              |              |              |           |          |                 |                      |
|                      | concrete block wall |                |         | no      |           |              |      |              |              |              |           |          |                 |                      |
|                      | plaster ceiling     |                |         | no      |           |              |      |              |              |              |           |          |                 |                      |
|                      | flex duct           |                |         | no      |           |              |      |              |              |              |           |          |                 |                      |
|                      | doors               | 2              | no      | assumed | x         |              |      | x            |              |              | x         |          | M:7             | N                    |

T=Thermal, S=Surfacing, M=Miscellaneous  
REM=Removed

6 Month Inspection; N=No Change, R=Repaired, D=Damaged,



Client: North Smithfield School Dept.  
Address: 450 Greenville Road  
North Smithfield, 02896

Warwick, RI Phone# (401) 461-3993  
ASBESTOS INSPECTION FORM

Project Inspector: Kenneth Beliveau

Contact: \_\_\_\_\_  
Project Location: **Haliwell Bldg #10 (was #8)**

Date: 12/30/05  
Type of Inspection: 6 month surveillance

| Location   | Suspect Material        | Approx. Amount | Friable | ACBM?   | No Damage | Phys. Damage |      | Accessible      | Phys. Damage | Water Damage | Potential |          | Response Action | 6 month Surveillance |
|------------|-------------------------|----------------|---------|---------|-----------|--------------|------|-----------------|--------------|--------------|-----------|----------|-----------------|----------------------|
|            |                         |                |         |         |           | <10%         | >10% |                 |              |              | Damage    | Sig. Dam |                 |                      |
| Gym        | 12x12 FT/A              | 3,800 sf       | no      | yes     |           | 2 sf         |      | x               | x            |              |           | x        | M3              | N                    |
|            | exterior Transite wall  | 300 sf         | no      | yes     | x         |              |      | x               |              |              | x         |          | M7              | N                    |
|            | window glazing          | 54 sf          | no      | yes     | x         |              |      | x               |              |              |           |          | M8              | N                    |
|            | doors                   | 7              | no      | assumed | x         |              |      | x               |              |              | x         |          | M7              | N                    |
| Stage      | exterior Transite walls | 400 sf         | no      | yes     | x         |              |      | x               |              |              | x         |          | M7              | N                    |
|            | window glazing          | 60 sf          | no      | yes     | x         |              |      | x               |              |              |           |          | M8              | N                    |
| Music Room | 9 X 9 FT/A              | 770 sf         | no      | assumed | x         |              |      | under carpeting |              |              |           |          | M8              | N                    |
|            | 2x4 CT fiss/pnhole      | 770 sf         | yes     | assumed | x         |              |      | x               |              |              | x         |          | M7              | N                    |
|            | window glazing          | 10 sf          | no      | yes     | x         |              |      | x               |              |              |           |          | M8              | N                    |
|            | doors                   | 2              | no      | assumed | x         |              |      | x               |              |              | x         |          | M7              | N                    |
|            | ceramic walls           | 600 sf         | no      | assumed | x         |              |      | x               |              |              |           |          | M8              | N                    |
|            | Transite ceiling        | 770 sf         | no      | yes     | x         |              |      | x               |              |              | x         |          | M7              | N                    |
|            | caulk board             |                | no      | assumed | x         |              |      | x               |              |              |           |          | M8              | N                    |
|            | chalk board             |                | no      | assumed | x         |              |      | x               |              |              |           |          | M8              | N                    |

T=Thermal, S=Surfacing, M=Miscellaneous  
REM=Removed

6 Month Inspection; N=No Change, R=Repaired, D=Damaged,

P.O. Box 772

Client: North Smithfield School Dept.

Warwick, RI Phone# (401) 461-3993

Project Inspector: Kenneth Beliveau

Address: 450 Greenville Road

ASBESTOS INSPECTION FORM

North Smithfield, 02896

Contact:

Date: 12/30/05

Project Location

Haliwell Bldg #10 (was #8)

Type of Inspection: 6 month surveillance

| Location             | Suspect Material             | Approx. Amount | Friable | ACBM?   | No Damage | Phys. Damage |      | Accessible | Phys. Damage | Water Damage | Potential |          | Response Action | 6 month Surveillance |
|----------------------|------------------------------|----------------|---------|---------|-----------|--------------|------|------------|--------------|--------------|-----------|----------|-----------------|----------------------|
|                      |                              |                |         |         |           | <10%         | >10% |            |              |              | Damage    | Sig. Dam |                 |                      |
| Kitchen/Storage Area | 1 X 1 CT large dot           |                |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                      | sheetrock wall               |                |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                      | green ceramic floor tile     | 30 sf          | no      | assumed | x         |              |      | x          |              |              |           |          | M 8             | N                    |
|                      | pink ceramic floor tile      | 30 sf          | no      | assumed | x         |              |      | x          |              |              |           |          | M 8             | N                    |
|                      | green ceramic wall tile      | 160 sf         | no      | assumed | x         |              |      | x          |              |              |           |          | M 8             | N                    |
|                      | pink ceramic wall tile       | 160 sf         | no      | assumed | x         |              |      | x          |              |              |           |          | M 8             | N                    |
|                      | 9 x 9 FT/A                   | 630 sf         | no      | yes     |           | 80sf         |      | x          | x            |              | x         |          | M 3             | N                    |
|                      | Transite ceiling             | 116 sf         | no      | yes     | x         |              |      | x          |              |              | x         |          | M 7             | N                    |
|                      | Transite wall                | 150 sf         | no      | yes     | x         |              |      | x          | x            |              | x         |          | M 7             | N                    |
|                      | window glazing               | 7 sf           | no      | yes     | x         |              |      | x          |              |              |           |          | M 8             | N                    |
| Boiler Room          |                              |                |         |         |           |              |      |            |              |              |           |          |                 |                      |
|                      | ceiling/wall plaster         |                |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                      | flex joint                   |                |         | no      |           |              |      |            |              |              |           |          |                 |                      |
|                      | glue dots                    | 10 sf          | no      | yes     | x         |              |      | x          |              |              | x         |          | M 7             | N                    |
|                      | metal jacketed exhaust stack | 60 sf          | yes     | assumed | x         |              |      | x          |              |              | x         |          | M 7             | N                    |
|                      | concrete floor               | 230 sf         | no      | assumed | x         |              |      | x          |              |              | x         |          | M 7             | N                    |

6 Month Inspection; N=No Change, R=Repaired, D=Damaged,

T=Thermal, S=Surfacing, M=Miscellaneous

REM=Removed

MEI Environmental, Inc  
P.O. Box 772

Client: North Smithfield School Dept.  
Address: 450 Greenville Road  
North Smithfield, 02896

Warwick, RI Phone# (401) 461-3993  
**ASBESTOS INSPECTION FORM**

Project Inspector: Kenneth Beliveau

Contact:

Date: 12/30/05

Project Location: **Haliwell Bldg #10 (was #8)**

Type of Inspection: 6 month surveillance

| Location                          | Suspect Material       | Approx. Amount | Friable | ACBM?   | No Damage | Phys. Damage |      | Accessible      | Phys. Damage | Water Damage | Potential |          | Response Action | 6 month Surveillance |
|-----------------------------------|------------------------|----------------|---------|---------|-----------|--------------|------|-----------------|--------------|--------------|-----------|----------|-----------------|----------------------|
|                                   |                        |                |         |         |           | <10%         | >10% |                 |              |              | Damage    | Sig. Dam |                 |                      |
| Reading Room adjacent to Boys Rm. | 9 x9 FT/A              | 130 sf         | no      | assumed | unknown   |              |      | under carpeting |              |              |           |          | M8              | N                    |
|                                   | 2 x 4 CT fiss/pinhole  | 130 sf         | yes     | assumed |           | 6 sf         |      | x               | x            |              |           | x        | M3              | N                    |
|                                   | Transite ceiling       | 230 sf         | no      | yes     |           | 5 sf         |      |                 | x            |              |           | x        | M5              | N                    |
|                                   | ceramic flooring       | 100 sf         | no      | assumed | x         |              |      | x               |              |              |           |          | M8              | N                    |
|                                   | ceramic walls          |                | no      | assumed | x         |              |      | x               |              |              |           |          | M8              | N                    |
|                                   | window glazing         | 2 sf           | no      | yes     | x         |              |      | x               |              |              |           |          | M8              | N                    |
|                                   | off white base molding | 46 lf          | no      | assumed | x         |              |      | x               |              |              | x         |          | M7              | N                    |
|                                   | doors                  | 1              | no      | assumed | x         |              |      | x               |              |              | x         |          | M7              | N                    |
|                                   |                        |                |         |         |           |              |      |                 |              |              |           |          |                 |                      |
| Front Hall including closets      | 9 x9 FT/A              | 125 sf         | no      | yes     | x         |              |      | x               |              |              | x         |          | M7              | N                    |
|                                   | 1 x 1 CT large dot     |                |         | no      |           |              |      |                 |              |              |           |          |                 |                      |
|                                   | Transite ceiling       | 370 sf         | no      | yes     | unknown   |              |      |                 |              |              | x         |          | M7              | N                    |
|                                   | ceramic flooring       | 370 sf         | no      | assumed | x         |              |      | x               |              |              |           |          | M8              | N                    |
|                                   | Doors                  | 6              | no      | assumed | x         |              |      | x               |              |              | x         |          | M7              | N                    |
|                                   | window glazing         | 5 sf           | no      | yes     | x         |              |      | x               |              |              |           |          | M8              | N                    |
|                                   |                        |                |         |         |           |              |      |                 |              |              |           |          |                 |                      |

T=Thermal, S=Surfacing, M=Miscellaneous  
REM=Removed

6 Month Inspection; N=No Change, R=Repaired, D=Damaged,

MEI Environmental, Inc  
P.O. Box 772  
Warwick, RI Phone# (401) 461-3993  
ASBESTOS INSPECTION FORM

Client: North Smithfield School Dept.  
Address: 450 Greenville Road  
North Smithfield, 02896

Project Inspector: Kenneth Belyeat

Contact:   
Project Location: Halliwell Bldg #10 (was #8)

Date: 12/30/05  
Type of Inspection: 6 month surveillance

| Location                   | Suspect Material      | Approx. Amount | Friable | ACBM?   | No Damage | Phys. Damage |       | Accessible | Phys. Damage | Water Damage | Potential |         | Response Action | 6 month Surveillance |
|----------------------------|-----------------------|----------------|---------|---------|-----------|--------------|-------|------------|--------------|--------------|-----------|---------|-----------------|----------------------|
|                            |                       |                |         |         |           | <10%         | >10%  |            |              |              | Damage    | Sig Dam |                 |                      |
| Room adjacent to Girls Rm. | 9 x9 FT/A             | 140 sf         | no      | yes     | x         |              |       | x          |              |              | x         |         | M7              | N                    |
|                            | 2 x 4 CT fiss/pinhole | 140 sf         | yes     | assumed |           |              | 24 sf | x          |              | x            | x         |         | M5              | N                    |
|                            | Transite ceiling      | 180 sf         | no      | yes     | x         |              |       | x          |              |              | x         |         | M7              | N                    |
|                            | ceramic flooring      |                | no      | assumed | x         |              |       | x          |              |              |           |         | M8              | N                    |
|                            | ceramic walls         |                | no      | assumed | x         |              |       | x          |              |              |           |         | M8              | N                    |
|                            | window glazing        | 2 sf           | no      | yes     | x         |              |       | x          |              |              |           |         | M8              | N                    |
|                            | doors                 | 4              | no      | assumed | x         |              |       | x          |              |              | x         |         | M7              | N                    |
|                            |                       |                |         |         |           |              |       |            |              |              |           |         |                 |                      |
| Boys Lav                   | flooring material     | 90 sf          | no      | assumed | x         |              |       | x          |              |              | x         |         | M7              | N                    |
|                            | 2 x 2 CT fiss/pinhole |                |         | no      |           |              |       |            |              |              |           |         |                 |                      |
|                            | Transite ceiling      |                |         |         |           |              |       |            |              |              |           |         | REM             | N                    |
|                            | ceramic walls         | 72 sf          | no      | assumed | x         |              |       | x          |              |              |           |         | M8              | N                    |
|                            | Doors                 | 1              | no      | assumed | x         |              |       | x          |              |              | x         |         | M7              | N                    |
|                            | window glazing        | 3 sf           | no      | yes     | x         |              |       | x          |              |              |           |         | M8              | N                    |
|                            | stall partitions      | 60 sf          | no      | assumed | x         |              |       | x          |              |              | x         |         | M7              | N                    |
|                            | counter top           | 18 sf          | no      | assumed | x         |              |       | x          |              |              | x         |         | M7              | N                    |

T=Thermal, S=Surfacing, M=Miscellaneous  
REM=Removed  
6 Month Inspection; N=No Change, R=Repaired, D=Damaged,



Client: North Smithfield School Dept.  
Address: 450 Greenville Road  
North Smithfield, 02896

Warwick, RI Phone# (401) 461-3993  
ASBESTOS INSPECTION FORM

Project Inspector:

Kenneth Beliveau

Contact: Haliwell (Building # 8)  
Project Location:

Date: 12/30/05

Type of Inspection: 6 month surveillance

| Location       | Suspect Material      | Approx. Amount | Friable | ACBM?   | No Damage | Phys. Damage |      | Accessible | Phys. Damage | Water Damage | Potential |         | Response Action | 6 month Surveillance |
|----------------|-----------------------|----------------|---------|---------|-----------|--------------|------|------------|--------------|--------------|-----------|---------|-----------------|----------------------|
|                |                       |                |         |         |           | <10%         | >10% |            |              |              | Damage    | Sig Dam |                 |                      |
| Girls Lav      | flooring material     | 144 sf         | no      | assumed | x         |              |      | x          |              |              |           |         | M8              | N                    |
|                | 2 x 2 CT fiss/pinhole |                |         | no      |           |              |      |            |              |              |           |         |                 |                      |
|                | Transite ceiling      |                |         |         |           |              |      |            |              |              |           |         | REM             |                      |
|                | ceramic walls         | 96 sf          | no      | assumed | x         |              |      | x          |              |              |           |         | M8              | N                    |
|                | stall partitions      | 150 sf         | no      | assumed | x         |              |      | x          |              |              | x         |         | M7              | N                    |
|                | window glazing        | 4 sf           | no      | yes     | x         |              |      | x          |              |              |           |         | M8              | N                    |
|                | doors                 | 4              | no      | assumed | x         |              |      | x          |              |              | x         |         | M7              | N                    |
|                | counter top           | 18 sf          | no      | assumed | x         |              |      | x          |              |              | x         |         | M7              | N                    |
|                |                       |                |         |         |           |              |      |            |              |              |           |         |                 |                      |
| Exterior       | roof shingles         | 10,400         | no      | assumed | x         |              |      |            |              |              |           |         | M8              | N                    |
|                | roof mastic           | 10 sf          | no      | assumed | x         |              |      |            |              |              |           |         | M8              | N                    |
|                | Transite ceiling      | 1,000 sf       | no      | yes     |           |              | 8 sf | x          | x            |              |           | x       | M3              | N                    |
|                |                       |                |         |         |           |              |      |            |              |              |           |         |                 |                      |
| Above Ceilings | duct insulation       | 100 sf (est.)  | yes     | assumed | probable  |              |      |            | x            |              |           | x       | T5              | N                    |
|                |                       |                |         |         |           |              |      |            |              |              |           |         |                 |                      |
|                |                       |                |         |         |           |              |      |            |              |              |           |         |                 |                      |
|                |                       |                |         |         |           |              |      |            |              |              |           |         |                 |                      |

T=Thermal, S=Surfacing, M=Miscellaneous  
REM=Removed  
6 Month Inspection; N=No Change, R=Repaired, D=Damaged,